







NO	ASSY NO.	PART NO.	PART NAME	MATERIAL	FINISH
1	MG641295	MG671293	SSD-3F HOUSING	PBT	GRAY
2		P900694	SSD-3P INNER SEAL	SILICON	RED

NO	ASSY NO.	PART NO.	PART NAME	MATERIAL	FINISH
1	MG641295S-4	MG671293	SSD-3F HOUSING	PBT	GRAY
2		P900694	SSD-3P INNER SEAL	SILICON	BLACK



SECTION A-A



DETAIL B (S=5/1)
(TERMINAL 삽입부 DIMENSION)

NOTE

- MUST BE FREE OF FLASH, SINK AND IMPERFECTION THAT AFFECT FUNCTION.
- APPLICABLE PART : SSD FEMALE TERMINAL (ST730622)
SSD 3P REAR HOLDER (MG631233)
- 6 HAZARDOUS SUBSTANCES IN PARTS (LEAD, MERCURY, CADMIUM, HEXAVALENT CHROMIUM, PBBs, PBDEs) SHALL NOT EXCEED THE MAXIMUM PERMISSIBLE CONCENTRATION PRESCRIBED UNDER EU ELV DIRECTIVE & RoHS REGULATION.

주 기

- 기능상 유해한 BURR 및 WELDLINE등이 없을것.
- 적용부품 : SSD FEMALE TERMINAL (ST730622)
SSD 3P REAR HOLDER (MG631233)
- 제품내 함유된 6대 유해물질 (납, 수은, 카드뮴, 6가크롬, PBBs, PBDEs)은 EU ELV 지침 및 RoHS 법규에서 지정한 최대 허용 농도를 초과해서는 안된다.

ECO-1303-014에 근거 도면 제작성	Y.M.K	CSH	HSH	'13.03.05
설계사양변경(S090096)근거 도면 제작성 (TERMINAL 역삽입 개선 위한 형상 변경)	BJG			'09.04.24
설계사양변경(S060092)근거 도면 제작성 (TERMINAL 역삽입 개선 위한 형상 변경)	KBS			'06.04.05
설계사양변경(S060080)근거 도면 제작성 ("M" 마크 표기)	KBS			'06.03.07
시방변경(S040207)근거 도면 제작성	KDJ			'04.12.06
LTR	DR.	CHK.	APP.	DATE

5	시방변경(S040123)근거 도면 제작성	KDJ	WF	'04.09.13	
4	시방변경(S040081)근거 도면 제작성	KDJ	WF	'04.07.01	
3	고객요청에 의한 치수 추가	OJM	KO	'00.11.10	
2	시방변경(000128)에 의한 수정		WF	'00.08.16	
1	CU요청('98.11.30회의록)에 의한 도면 제작성	K.J.LEE	WF	'98.12.02	
LTR	REVISION RECORD	DR.	CHK.	APP.	DATE
DR. JANG 97.12.03		CHK.	WF 12/3	12/4	
CHK. S.I. SAKEP 12/4		APP.	WF 12/5		

MATERIAL	SEE TABLE	KOREA ELECTRIC TERMINAL CO., LTD. Product Development Team 1
FINISH	SEE TABLE	
WIRE RANGE		CLASS
INSULATION		TYPE
TOLERANCE EXCEPT AS NOTED	SEE TABLE	SCALE 2/1
PART NAME	SSD 3F HOUSING ASSY(B)	
PART NO.	MG641295 MG641295S-4	

APPROVED

2017-08-10

KOREA ELECTRIC
TERMINAL CO., LTD.
Product Development Team 1

ISSUE MARK