





- NOTE**
- 1. MUST BE FREE OF BURR, WELDLINE AND IMPERFECTION THAT AFFECT FUNCTION.
 - 2. APPLICABLE CONNECTOR : MG651050,MG612231
 - 3. APPLICABLE CLIP : 090II CLIP
 - ③4. 6 HAZARDOUS SUBSTANCES IN PARTS (LEAD, MERCURY, CADMIUM, HEXAVALENT CHROMIUM, PBBs, PBDEs) SHALL NOT EXCEED THE MAXIMUM PERMISSIBLE CONCENTRATION PRESCRIBED UNDER EU ELV DIRECTIVE & RoHS REGULATION.




GENERAL TOLERANCE (HOUSING)							USED ON
10MAX	50MAX	100MAX	250MAX	250VR	ANGLE	ECCENT	
±0.2	±0.3	±0.55	±0.95	±1.4	±30'	0.1	

- 주 기**
- 1. 기능상 유해한 BURR 및 WELDLINE등이 없을것.
 - 2. 적용 CONNECTOR : MG651050,MG612231
 - 3. 적용 CLIP : 090II CLIP
 - ③4. 제품내 함유된 6대 유해물질 (납, 수은, 카드뮴, 6가크롬, PBBs, PBDEs)은 EU ELV 지침 및 RoHS 법규에서 지정한 최대 허용 농도를 초과해서는 안된다.



③	P901320	090II JOINT TAB 8WAY- 2열	BRASS	PRE-TIN
②	MG672488-7	090II JOINT 8P R/HOLDER	PBT	BROWN
①	MG673308-2	090II JOINT 8P HOUSING	PBT	BLUE
NO.	PART NO.	PART NAME	MATERIAL	FINISH

						MATERIAL		SEE TABLE	 KOREA ELECTRIC TERMINAL CO., LTD.
						FINISH		SEE TABLE	
③	ECO-1610-046 근거 도면 재작성	YTK	CJH	LSY	'16.10.12	WIRE RANGE			CLASS
②	CLIP 매칭 부 유격 축소 (ECO-1409-006) 근거	ASY	HYJ	LSY	'14.09.01	INSULATION			TYPE
①	설계사양변경(S070017)근거 도면 재작성 (CLIP LOCK부 형상변경)	KBS	※	※	'07.01.23	TOLERANCE EXCEPT AS NOTED		SCALE 2/1	PART NO. MG643309-2
LTR	REVISION RECORD	DR.	CHK.	APP.	DATE				
DR. KYM 04.10.06		CHK.				PART NAME			
10/18		APP.		10/19		090II JOINT 8P ASSY			

APPROVED

2017-08-10

**KOREA ELECTRIC
TERMINAL CO., LTD.**
Korea Electric Te
rminal Co., LTD.

ISSUE MARK